

PRIORITY

TOP SECRET 192000Z

PRIORITY

INFO PRIORITY

25X1

3354

25X1

FOLG REPORT RECD FROM

NRO Review Completed.

ITERIM REPORT NO. 6

25X1

1. THE COMMUTATOR IN [REDACTED] FAILED ON [REDACTED] RESULTING IN THE LOSS OF DATA FROM [REDACTED]. THE COMMUTATOR FAILED TO START FOR AN UNKNOWN REASON ON [REDACTED] READ IN. THE SYSTEM TEMP ON [REDACTED] DEGREES F AND THE VOLTAGE WAS NORMAL AT 24 VDC. NO DATA ARE AVAILABLE AFTER READ OUT [REDACTED] SO IT IS NOT YET KNOWN IF THE COMMUTATOR RESUMED OPERATION DURING LATER [REDACTED] MISSION. UNLESS THE COMMUTATOR RESUMED OPERATION, THERE WILL BE NO DATA AFTER [REDACTED].

25X1

25X1

25X1

25X1

25X1

25X1

2. ALL DATA THROUGH [REDACTED] HAVE BEEN ANALYZED. NO RPT NO SIGNALS OF INTEREST NOTED.

3. [REDACTED] WAS LAUNCHED ON [REDACTED] AT 2036 ZULU ON [REDACTED] NO DATA ARE AVAILABLE YET TO DETERMINE IF THE SYSTEM IS FUNCTIONING PROPERLY.

25X1

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

Excluded
downgrading and
declassification